


Parameters

Emissivity	0.95
Refl. temp.	10 °C
Distance	1 m
Atmospheric temp.	20 °C
Ext. optics temp.	20 °C
Ext. optics trans.	1
Relative humidity	50 %

06.03.2018. 14:07:42



FLIR1662.jpg

FLIR E8

63901624

06.03.2018. 14:07:42



FLIR1662.jpg

FLIR E8

63901624


Ēkas termogramma.

Siltuma zudumi caur norobežojošām konstrukcijām, būvelementu termiskie tilti.

Parameters

Emissivity	0.95
Refl. temp.	10 °C
Distance	1 m
Atmospheric temp.	20 °C
Ext. optics temp.	20 °C
Ext. optics trans.	1
Relative humidity	50 %

06.03.2018. 14:08:04



FLIR1666.jpg

FLIR E8

63901624

06.03.2018. 14:08:04



FLIR1666.jpg

FLIR E8

63901624


Ēkas termogramma.

Siltuma zudumi caur norobežojošām konstrukcijām, būvelementu termiskie tilti.

Parameters

Emissivity	0.95
Refl. temp.	10 °C
Distance	1 m
Atmospheric temp.	20 °C
Ext. optics temp.	20 °C
Ext. optics trans.	1
Relative humidity	50 %

06.03.2018. 14:08:18



FLIR1670.jpg

FLIR E8

63901624

06.03.2018. 14:08:18



FLIR1670.jpg

FLIR E8

63901624


Ēkas termogramma.

Siltuma zudumi caur norobežojošām konstrukcijām, būvelementu termiskie tilti.

Parameters

Emissivity	0.95
Refl. temp.	10 °C
Distance	1 m
Atmospheric temp.	20 °C
Ext. optics temp.	20 °C
Ext. optics trans.	1
Relative humidity	50 %

06.03.2018. 14:08:21



FLIR1672.jpg

FLIR E8

63901624

06.03.2018. 14:08:21



FLIR1672.jpg

FLIR E8

63901624


Ēkas termogramma.

Siltuma zudumi caur norobežojošām konstrukcijām, būvelementu termiskie tilti.

Parameters

Emissivity	0.95
Refl. temp.	10 °C
Distance	1 m
Atmospheric temp.	20 °C
Ext. optics temp.	20 °C
Ext. optics trans.	1
Relative humidity	50 %

06.03.2018. 14:08:47



FLIR1678.jpg

FLIR E8

63901624

06.03.2018. 14:08:47



FLIR1678.jpg

FLIR E8

63901624


Ēkas termogramma.

Siltuma zudumi caur norobežojošām konstrukcijām, būvelementu termiskie tilti.

Parameters

Emissivity	0.95
Refl. temp.	10 °C
Distance	1 m
Atmospheric temp.	20 °C
Ext. optics temp.	20 °C
Ext. optics trans.	1
Relative humidity	50 %

06.03.2018. 14:09:03



FLIR1680.jpg

FLIR E8

63901624

06.03.2018. 14:09:03



FLIR1680.jpg

FLIR E8

63901624

Ēkas termogramma.

Siltuma zudumi caur norobežojošām konstrukcijām, būvelementu termiskie tilti.